

Date	Recording Tach/ Hour Meter Time	Total Time In Service	Description of work performed
5-6-09	1	1	Installed new FRANKLIN O-235 engine Serial # 20113 00099 P2L 235 BB1 130HP
5-22-09	6	6	3.9 gph w/ Marvel carb leaned at 3500 feet w/ Wood Prop 1950 RPM cruise 90 mph
6-6-09	13	13	Repitched wood prop, max rpm 2400
7-8-09	20	20	Replaced cracked ex. manifold
7-8-09	20	20	Engine in Phase II
11-25-09	37	37	Repitched Wood prop now 2600 in flight, 2300 static
12-1-09	43	43 Compr. ck	#1-79, #2-72, #3-74, #4-73
9-29-10	121,2	121,2	Changed Oil 6 Q Aeroshell 100w
			CUT Oil Filter - no metal found
			replaced Oil Filter with Napg 1515
			Compression check:
			#1-78 #2-73 #3-74 #4-74

Date	Recording Tach/ Hour Meter Time	Total Time In Service	Description of work performed
9-29-10	121.2	121.2	I certify that the engine has been
			inspected to in accordance with the scope and detail of
			appendix D to part 43 and has been found to be in a
			condition for safe operation
			Chris Boules 3374803 Repairman

